

NAVCO® REPAIR PROGRAM

For **NAVCO®** Pneumatic Piston Vibrators with piston diameters of 3 inches or larger, a Rebuild Program for worn or damaged units is offered. This procedure involves the following operations:

1. Rebore housing to new tolerance
2. Insert oversized piston
3. Install new gasket and head plate
4. Test to new specifications
5. Repaint unit

To take advantage of **NAVCO®**'s Repair Program, we ask that you contact **NAVCO®** and advise that the vibrator(s) are being returned to **NAVCO®** for evaluation. The unit(s) should be returned to **NAVCO®** freight **PREPAID**. Boxes or Vibrators should be clearly marked with customer contact information.

Upon receipt of the vibrator(s), the units will be examined to determine if they are repairable. After this examination, you will be notified of the condition of the vibrator and your available options. Please note that **NAVCO®** Pneumatic Piston Vibrators are eligible for repair only once. Previously repaired units are stamped "REPD" on the head plate (indicating a repaired unit).

Huntsman, Inc. ▼ 2362 Warren Ave. ▼ Twin Falls, Idaho 83301
(877) 733-2214 ▼ (208) 733-2214 ▼ Fax (208) 733-2240
www.huntsmaninc.com ▼ mail@huntsmaninc.com